

GOVERNMENT OF ANDHRA PRADESH

ABSTRACT

Secretariat Buildings – General Administration Department – Replacement of damaged UG cable with main cable from 'J' Block substation to ground floor north 'H' Block and providing of main panel in the Ground floor - 'H' Block in the premises of A.P. Secretariat Hyderabad – Administrative Sanction – Orders – Issued.

=====

GENERAL ADMINISTRATION (SB.I) DEPARTMENT

G.O.Rt.No. 4807

Dated: 13.10.2012

Read:-

From the Chief Engineer (R&B), Buildings & CRF, Errammanzil, A.P.,
Hyderabad, Letter. No. DEE /Elect / Sectt Blgs/Hyd/2012, Vol-2.
Dated: 05.09.2012.

ORDER:

In the circumstances reported by the Chief Engineer (R&B) Buildings & CRF, Errammanzil, A.P. Hyderabad in the reference read above and after examination of the matter, Government hereby accord administrative sanction for an amount of Rs.11,00,000/- (Rupees Eleven Lakhs only) for replacement of damaged UG cable with main cable from 'J' Block substation to Ground floor north 'H' Block and providing of main panel in the ground floor 'H' Block in the premises of A.P. Secretariat Hyderabad on the responsibility of Electrical Engineer (GL) (R&B) Hyderabad subject to following due procedure and also subject to production of the work done certificate at the time of issue of L.O.C.

2. The expenditure shall be debited to the head of account "2059 Public works - 01 Office buildings - MH 053 Maintenance and repairs – SH (10) Buildings of General Administration Department - 270 Minor works - 272 Maintenance"

3. This order does not require the concurrence of Finance Department as per rules in force.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

AJAY MISRA

PRL. SECRETARY TO GOVT. (POLL.)

To

The Chief Engineer (R&B); Buildings, Hyderabad.

The Electrical Engineer (General), R&B, AC Guards, Hyderabad.

The Dy. Executive Engineer (Electrical), Sectt. Sub-division, Hyderabad.
SF/SC.

// FORWARDED : : BY ORDER //

SECTION OFFICER